

**Butler Avenue, S.E.**

1201            03/16/94    8393

1308 W.        07/21/2000 9007            VanderVelde

1312            05/14/75    4851            Cannon  
1 ½-story frame dwelling. Plug in basement.

1313            01/31/62    863            Capitol  
Sewer line to be used.

1313 E. Butler S.E. Built about 1962, the Oakdale Park Christian Reformed Church was found to have serious structural damage shortly after the heavy New Year's snowfall in 1999. Roof beams were cracking, and the building was deemed in imminent danger of collapse. The church was immediately condemned by City inspectors, and the congregation had the structure demolished as a hazard to the surrounding neighborhood.

1313 E.        01/19/99    8857            Pitsch

*1317 E.*

1318 W.        10/04/66    2270            R. Velting Excavating Co.

1320 W.        10/04/66    2271            R. Velting Excavating Co.

1326 W.        03/16/2001 9062            VanderKodde  
House owned by Oakdale Park Christian Reformed Church.

1327 E.        05/10/2001 9078            VanderKodde